



Threat Update Service* Advisory October 6, 2013

Purpose: The Corero Security Active Response Team informs customers that the IPS 5500 has proactive coverage against known attacks targeting the GE Proficy Cimplicity WebView substitute.bcl Directory Traversal Vulnerability.

Issue: A directory traversal vulnerability exists in substitute.bcl in the WebView CimWeb subsystem in GE Intelligent Platforms Proficy. This could allow an attacker to gain access to sensitive information by reading arbitrary files.

Recommended Action: Enable the specified rule and ensure that the rule is used to inspect traffic to the affected product infrastructure.

Issue Identifier	CVE-2013-0653
Advisory	http://www.us-cert.gov/control_systems/pdf/ICSA-13-022-02.pdf
Risk Assessment	Important Vulnerability
Threat Impact	Remotely exploitable vulnerability that could allow an attacker to gain access to sensitive information.
Affected Products	GE Intelligent Platforms Proficy HMI/SCADA - CIMPLICITY 4.01 through 8.0 Proficy Process Systems with CIMPLICITY
Corero Products	IPS 5500 E-Series v5.34 (build 005 and later), v6.60 (build 047 and later), v6.61 (build 021 and later), v6.80 (build 035 and later).
Associated Rule	tln-102033
Associated Rule Set	This rule is automatically enabled in the "Strict Server Protection" rule set.

* previously called TopResponse

<https://support.corero.com> Corero Network Security, Inc.
One Cabot Road, Hudson, MA 01749 +1 978.212.1500 • Fax +1 978.212.1600
• USA • Japan • Asia Pacific • EMEA Copyright 2013. All Rights Reserved.